


Heater coil specification plate with no evidence of re-inspection dates



External corrosion on condensate storage tank



Filter separator specification plate with no evidence of re-inspection dates



Plant skid showing external corrosion